

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Spring 2014 Levee Inspection Results****Sacramento Maintenance Yard East Levee Yolo Bypass**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
**SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

**FALL INSPECTIONS:** The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2014 Levee Inspection Results**

**Sacramento Maintenance Yard East Levee Yolo Bypass**

Waterway			Bank	Unit Miles
Unit No. 01 Yolo Bypass			Left	2.00
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	03/11/2014 - 03/11/2014			
DWR Inspector	John Williamson			
Accompanied By	Ted Skidgel Sacramento Maintenance Yard			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Sacramento Maintenance Yard East Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.00	03/11/2014 03/11/2014	John Williamson

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals				°
					°
DWR ID	DWR_ST0004_01_s _ 2013_3				
Action/Comments					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment				°
					°
DWR ID	DWR_ST0004_01_s _ 2013_4				
Action/Comments					

No Photos

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training				°
					°
DWR ID	DWR_ST0004_01_s _ 2013_5				
Action/Comments					

No Photos

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2014**

**Sacramento Maintenance Yard East Levee Yolo Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Left	2.00	03/11/2014 03/11/2014	John Williamson

LM Start	0.00	Rating **	A	Issue No.	56
LM End	2.00	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.763833 °	38.735970 °
				-121.635498 °	-121.633663 °
DWR ID	DWR_ST0004_01_s _ 2014_56				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					


Photo 1 of 1 : johngw\_s\_20140317\_631.jpg



The vegetation on slope is 75% grasses and complies with standards.  
Spring 2014

LM Start	0.01	Rating **	A/W	Issue No.	11
LM End	0.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.765295 °	38.762751 °
				-121.635085 °	-121.635422 °
DWR ID	DWR_ST0004_01_f _ 2013_11				
Action/Comments					
Trees / Woody Vegetation					

Photo 1 of 1 : johngw\_s\_20140317\_633.jpg



The trees at Fremont Weir need to be monitored for future removal if necessary. Spring 2014

LM Start	0.01	Rating **	A	Issue No.	55
LM End	2.00	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.765290 °	38.735972 °
				-121.635081 °	-121.633663 °
DWR ID	DWR_ST0004_01_s _ 2014_55				
Action/Comments					
Control annual grass and weeds on the levee slopes and easements.					

Photo 1 of 1 : johngw\_s\_20140317\_632.jpg



The vegetation on the slope is 75% grasses and complies with standards. Spring 2014

\* Location  
LS : Land Side  
WS : Water Side  
CR : Crown

\*\* Rating  
A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

+ Issue Type  
Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement